

Note de service – Memo

29 août 2025

À : Toutes les unités de soins
De : Loïca Ducheine, Conseillère en soins infirmiers – Produits
Sujet : GRM 1002313/ Tube conique pour analyse d'urine

English below

Bonjour,

Nous tenons à vous informer qu'il y a une rupture de stock pour les tubes coniques utilisés pour les analyses d'urine jusqu'à la mi-septembre 2025. Par conséquent, nous devrons temporairement utiliser un produit de substitution. Ce produit est muni d'un bouchon à pression et ne peut pas être acheminé par le système de tubes pneumatiques (STP). Ces prélèvements doivent être remis en main propre au laboratoire central en raison du risque élevé de fuite. Nous vous rappelons également que le **réipient utilisé pour les analyses d'urine n'a pas besoin d'être stérile**. Le laboratoire évaluera un meilleur produit de substitution au cours de la semaine prochaine afin d'éviter que cette situation ne se reproduise à l'avenir.

Hello,

We would like to inform you that there is a stock shortage of conical tubes used for urine analysis until mid-September 2025. As a result, we will have to temporarily use a substitute product. This product has a pressure cap and cannot be sent via the pneumatic tube system (PTS). These specimens must be delivered by hand to the central laboratory due to the high risk of leakage. We would also like to remind you that the **container used for urine analysis does not need to be sterile**. The laboratory will evaluate a better substitute product over the next week to prevent this situation from recurring in the future.



Central Laboratory - Glen Site: Urine Conical Tubes With Push Cap Closure

Urine Conical Tubes With Push Cap Closure

The Central Laboratory of the **MUHC** – Glen Site wishes to inform you that urine conical tubes with a push cap closure cannot be transported by the Pneumatic Tube System (PTS). **These specimens must be delivered by hand to the Central Laboratory**. There is a high risk of leakage if transported via the PTS as the caps can become loosened or displaced. A specimen leak in the PTS will cause a shutdown of the PTS system for decontamination.

Thank you for your understanding.

Si vous avez des questions ou préoccupations, veuillez contacter / If you have any questions or concerns, please contact purchasing.clinical@muhc.mcgill.ca.